Basel Mission Archives

"Dammbruch eines Wasserbehälters in Hongkong. "

Title:	"Dammbruch eines Wasserbehälters in Hongkong. "
Alternate title:	Bursting of a dam in Hongkong.
Ref. number:	QA-30.113.0006
Creator:	[leer] N
Date:	Date late: 31.12.1901 Proper date: 01.01.1887-31.12.1901 Acquisition year: 2007
Description:	It is very likely that the image was taken shortly after the heavy rain event of 29-30 May 1889. The damage shown is described here: Report on Great Storm of the 29th and 30th May, 1889 (Hong Kong Government Reports Online: https://sunzi.lib.hku.hk/hkgro/view/s1889/1250.pdf)
Subject:	[Individuals]: [leer] N [Photographers / Photo Studios]: [leer] N [Geography]: Asia {continent}: China {modern state}: Hong Kong

Basel Mission Archives

(Xianggang) Special Administrative Region {province}: Hong Kong, general {place}
[Themes]: environment: physical environment: bay
[Themes]: conflicts - destruction and disaster: destruction
[Themes]: conflicts - destruction and disaster: flood
[Themes]: environment: physical environment: mountain
[Themes]: economy and daily life: water supply: pond
[Themes]: environment: physical environment: sea
[Themes]: travel and transport: means and types of transport: ship
[Themes]: special objects and materials: materials: rock
[Archives catalogue]: Images: QA: QA-30: untitled

Type: Still Image

Format:
[Format]: 21.4cm x 28.9cm
[Condition]: medium
[Type of support]: [leerl] W 1201
[Process]: b/w positive, paper print, albumen

Ordering: Please contact us by email info@bmarchives.org

Contact details: Basel Mission Archives/ mission 21, Missionstrasse 21, 4003 Basel, tel. (+41 61 260 2232), fax: (+41 61 260 2268), info@bmarchives.org